

ENTERED

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. W 064382

UNIQUE WELL I.D. # ABN 083

Water Right Permit No. 31-3E-18N

(1) OWNER: Name TR CAMANO INC Address PO Box 673 STANWOOD WA 98292

(2) LOCATION OF WELL: County ISLAND SO SW 1/4 SW 1/4 Sec 18 T. 31 N., R. 3E W.M.

(2a) STREET ADDRESS OF WELL (or nearest address) 966 E CAMANO DR CAMANO ISL

(3) PROPOSED USE: ☒ Domestic ☐ Industrial ☐ Municipal ☐
☐ Irrigation ☐ Test Well ☐ Other ☒
☐ DeWater

(4) TYPE OF WORK: Owner's number of well (if more than one) _____
Abandoned ☐ New well ☒ Method: Dug ☐ Bored ☐
Deepened ☒ Cable ☐ Driven ☐
Reconditioned ☐ Rotary ☒ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 180 feet. Depth of completed well 178 ft.

(6) CONSTRUCTION DETAILS:
Casing installed: 6 ft. Diam. from 12 ft. to 168 ft.
Welded ☐ ft. Diam. from _____ ft. to _____ ft.
Liner installed ☐ ft. Diam. from _____ ft. to _____ ft.
Threaded ☐ ft. Diam. from _____ ft. to _____ ft.

Perforations: Yes ☐ No ☒
Type of perforator used _____
SIZE of perforations _____ in. by _____ in.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.

Screens: Yes ☒ No ☐
Manufacturer's Name NAGOAKA
Type SS Model No. _____
Diam. 5 3/8 Slot size 20 from 168 ft. to 178 ft.
Diam. _____ Slot size _____ from _____ ft. to _____ ft.

Gravel packed: Yes ☐ No ☒ Size of gravel _____
Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.
Material used in seal _____
Did any strata contain unusable water? Yes ☐ No ☒
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____ H.P. _____
Type: _____

(8) WATER LEVELS: Land-surface elevation above mean sea level _____ ft.
Static level 124 ft. below top of well Date 4/30/96
Artesian pressure _____ lbs. per square inch Date _____
Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes ☐ No ☐ If yes, by whom? _____
Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.

" " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test _____
Bailer test _____ gal./min. with _____ ft. drawdown after _____ hrs.
Airtest 160 gal./min. with stem set at 170 ft. for 1 hrs.
Artesian flow _____ g.p.m. Date _____
Temperature of water _____ Was a chemical analysis made? Yes ☒ No ☐

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
TOP SOIL	0	1
TAN CLAY	1	4
TAN HARD PAN	4	10
TAN SANDY CLAY	10	16
TAN SAND & GRAVEL	16	25
TAN GRAVEL	25	76
SAND & GRAVEL	76	85
TAN SAND	85	140
BLUE CLAY	140	150
SAND	150	160
SAND & GRAVEL w/ WATER	160	180

RECEIVED
THIS WELL MEET SIGHTING
CATERIN 8.09
MAY 06 1996
DEPT. OF ECOLOGY

Work Started 4/25/96 19. Completed 4/30/96 19

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME CAMANO WELL DRILLING
(PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address PO Box 432 STANWOOD WA 98292

(Signed) Jessie J. Vance License No. 0611
(WELL DRILLER)

Contractor's Registration No. CAMANO 14622 Date 4/30/96 19

(USE ADDITIONAL SHEETS IF NECESSARY)

Ecology is an Equal Opportunity and Affirmative Action employer. For special accommodation needs, contact the Water Resources Program at (206) 407-6600. The TDD number is (206) 407-6006.